Too many lines after sweeping. The excess lines are visible during 2D wireframe and Xray. But if it is in realistic visual style the excess lines (circles) are not visible. How do I fix the display during 2D wireframe and Xray?